

Published date	24/10/2017
Document number	SUPAIR_2017/10_001
Page number	1/2



OBJECT: LEAF (standard version) "A" and "C" line settings.



Problem description:

A few LEAF were produced with a slow flying configuration and to the maximum allowed for certification approval tolerance.



Concerned products or affected products:

LEAF in all sizes: XS, S, M, and L

Note: that LEAF-LIGHT is not affected.

Facts / Findings:

Parachutal phases were observed on a few manufactured "Leaf" while pulling "Ears" in non-accelerated f light mode - the wing will come out of the parachutal phase as soon as the "Ears" are reopened.

Continued on the next page ▶






Published date	24/10/2017
Document number	SUPAIR_2017/10_001
Page number	2/2

Procedure to follow:

Check the wing' serial number on the label located at the leading edge and inner part of the central cells.



People able to carry out the verification:



Delay:

As soon as possible, depend of the wing used

Recipients of this document:



Safety Release: SUPAIR_2017/10_001

